

# ISO/TS 16190:2013-07 (E)

Footwear - Critical substances potentially present in footwear and footwear components - Test method to quantitatively determine polycyclic aromatic hydrocarbons (PAH) in footwear materials

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Principle .....	1
4	Chemicals .....	1
5	Apparatus and materials .....	2
6	Procedure .....	3
6.1	Preparation of standard solutions .....	3
6.2	Sample preparation .....	4
6.3	Extraction .....	5
6.4	Determination .....	5
7	Quantification .....	5
8	Performance of the method .....	5
9	Test report .....	6