

# ISO 8300:2013-12 (E)

## Nuclear fuel technology - Determination of plutonium content in plutonium dioxide of nuclear grade quality - Gravimetric method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Principle .....</b>	<b>1</b>
<b>3</b>	<b>Interferences .....</b>	<b>1</b>
<b>4</b>	<b>Apparatus .....</b>	<b>1</b>
<b>5</b>	<b>Procedure .....</b>	<b>2</b>
<b>5.1</b>	<b>Handling of the sample at the sampling station .....</b>	<b>2</b>
<b>5.2</b>	<b>Tarring of crucibles .....</b>	<b>2</b>
<b>5.3</b>	<b>Sub-sampling .....</b>	<b>2</b>
<b>5.4</b>	<b>Heating .....</b>	<b>2</b>
<b>5.5</b>	<b>Additional measurements .....</b>	<b>2</b>
<b>6</b>	<b>Expression of result .....</b>	<b>3</b>
<b>6.1</b>	<b>Calculation of the gravimetric conversion factor .....</b>	<b>3</b>
<b>6.2</b>	<b>Calculation of impurity correction factor .....</b>	<b>3</b>
<b>6.3</b>	<b>Calculation of plutonium concentration .....</b>	<b>3</b>
<b>6.4</b>	<b>Repeatability .....</b>	<b>4</b>
<b>6.5</b>	<b>Systematic errors .....</b>	<b>4</b>
<b>7</b>	<b>Test report .....</b>	<b>4</b>
<b>Annex A (informative) Gravimetric conversion factor for the non-volatile impurities .....</b>		<b>5</b>