

ISO 17859:2015-09 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Measurement method of piezoelectric strain at high electric field

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions, and symbols	1
3.1	Terms and definitions	1
3.2	Symbols	2
4	Measuring environment	2
5	Specimens	2
5.1	General	2
5.2	Shape and size	3
5.3	Electrodes	3
5.4	Polarization	3
6	Principle	3
7	Measurement equipment	3
7.1	Equipment	3
7.2	Components of equipment	4
7.3	Environment of specimen holder	5
7.4	Calibration of measurement equipment	5
8	Measurement conditions	5
9	Measurement procedures	5
10	Calculations and results	6
11	Test report	6
Annex A (informative) Example of reference sample		8