

# ISO 19017:2015-12 (E)

## Guidance for gamma spectrometry measurement of radioactive waste

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3</b>	<b>Application .....</b>	<b>7</b>
3.1	General .....	7
3.2	Typical applications .....	7
<b>4</b>	<b>Measurement equipment .....</b>	<b>8</b>
4.1	General .....	8
4.2	Open detector geometry .....	8
4.3	Collimated detector geometry .....	10
4.4	Components of gamma measurement system .....	13
4.4.1	Mechanical equipment .....	13
4.4.2	Radiation detection equipment .....	14
4.4.3	Data acquisition and analysis unit .....	14
4.4.4	Electrical control .....	14
4.4.5	Additional equipment .....	14
<b>5</b>	<b>Calibration .....</b>	<b>14</b>
5.1	General .....	14
5.2	Peak energy and shape calibration of the gamma spectrometry system .....	15
5.3	Efficiency calibration of the gamma spectrometry system .....	15
5.4	Attenuation correction techniques .....	18
<b>6</b>	<b>Data evaluation .....</b>	<b>18</b>
6.1	Data processing steps .....	18
6.2	Calculation of net peak count rates .....	19
6.3	Calculation of gamma activity inventory of the waste package .....	20
6.4	Calculation of measurement uncertainty .....	20
6.5	Calculation of detection limit .....	21
<b>7</b>	<b>Quality assurance .....</b>	<b>23</b>
7.1	General .....	23
7.2	Record of calibration, validation, and waste measurements .....	23
7.3	Documentation and procedures .....	24
7.4	Quality control .....	24
7.5	Competence .....	25
<b>Annex A (informative)</b>	<b>Examples of application of the techniques and methods discussed within this International Standard .....</b>	<b>26</b>
<b>Bibliography .....</b>		<b>47</b>