

# ISO 105-G04:2016-06 (E)

## Textiles - Tests for colour fastness - Part G04: Colour fastness to nitrogen oxides in the atmosphere at high humidities

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Normative references</b> .....		1
3 <b>Principle</b> .....		1
4 <b>Apparatus and reagents</b> .....		1
5 <b>Conditioning</b> .....		3
6 <b>Test specimens</b> .....		3
7 <b>Procedure</b> .....		3
8 <b>Test report</b> .....		4
9 <b>Notes on humidity for testing</b> .....		4
<b>Annex A (normative) Test apparatus</b> .....		5
<b>Bibliography</b> .....		7