

ISO 17973:2016-09 (E)

Surface chemical analysis - Medium-resolution Auger electron spectrometers - Calibration of energy scales for elemental analysis

| Contents | | Page |
|--------------------|---|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Symbols and abbreviated terms | 1 |
| 5 | Outline of method | 2 |
| 6 | Energy scale calibration procedures | 3 |
| 6.1 | Obtaining reference samples | 3 |
| 6.2 | Mounting samples | 3 |
| 6.3 | Cleaning samples | 3 |
| 6.4 | Choosing spectrometer settings for energy calibration | 5 |
| 6.5 | Operating the instrument | 5 |
| 6.6 | Measurement of reference peaks | 6 |
| 6.7 | Determining measured kinetic energies of reference peaks | 7 |
| 6.8 | Determining correction of instrument kinetic energy scale | 8 |
| 6.9 | Next calibration | 9 |
| Bibliography | | 11 |