

# ISO 10675-1:2016-12 (E)

## Non-destructive testing of welds - Acceptance levels for radiographic testing - Part 1: Steel, nickel, titanium and their alloys

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Radiographic technique .....	2
5	Acceptance levels .....	2
Annex A (informative) Guide to the limitations of radiographic testing .....		5
Annex B (informative) Examples for determination of area percentage (%) of imperfections .....		6
Annex C (informative) Calculation of the sum of acceptable areas .....		8
Bibliography .....		10