

ISO 14713-3:2017-04 (E)

Zinc coatings - Guidelines and recommendations for the protection against corrosion of iron and steel in structures - Part 3: Sherardizing

| Contents | | Page |
|--------------------|---|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Design for sherardizing | 2 |
| 4.1 | General | 2 |
| 4.2 | Surface preparation | 2 |
| 4.3 | Design considerations | 3 |
| 4.4 | Clearances of threaded components | 3 |
| 5 | Storage and transport | 4 |
| 5.1 | General | 4 |
| 5.2 | Recommendations for storage and transport | 4 |
| 6 | Effects of article condition on quality of sherardizing | 4 |
| 6.1 | Composition | 4 |
| 6.2 | Surface condition | 4 |
| 6.3 | Influence of steel surface roughness on the sherardized coating thickness | 5 |
| 6.4 | Internal stresses in the base material | 5 |
| 6.4.1 | General | 5 |
| 6.4.2 | Distortion cracking | 5 |
| 6.4.3 | Hydrogen embrittlement | 6 |
| 6.5 | Large objects and thick steels | 6 |
| 7 | Effect of sherardizing process on the article | 6 |
| 7.1 | Processing circumstances | 6 |
| 7.2 | Coating properties influenced by the sherardizing process | 6 |
| 7.2.1 | Sherardizing practice | 6 |
| 7.2.2 | Surface properties of the finished article | 6 |
| 8 | After-treatments | 7 |
| Bibliography | | 8 |