

DIN 50929-3:2018-03 (E)

Corrosion of metals - Corrosion likelihood of metallic materials when subject to corrosion from the outside - Part 3: Buried and underwater pipelines and structural components

Contents

	Page
Foreword	4
1 Scope	5
2 Normative references	5
3 Terms and definitions.....	6
4 Materials	6
5 Explanation of the assessment method	7
6 Estimating the likelihood of corrosion of materials in contact with soil.....	8
6.1 Unalloyed and low-alloy ferrous materials.....	8
6.1.1 General	8
6.1.2 Free corrosion in the absence of extensive concentration cells.....	8
6.1.3 Free corrosion in the presence of extensive concentration cells.....	11
6.1.4 Assessment of the effect of anodic and cathodic regions in the absence of external cathodes	11
6.1.5 Anodic corrosion due to galvanic cell formation in the presence of external cathodes.....	12
6.2 High-alloy stainless steels	13
6.3 Hot-dip galvanized steels.....	13
6.4 Copper materials	14
7 Estimating the likelihood of corrosion of materials in contact with water	15
7.1 Unalloyed and low-alloy ferrous materials.....	15
7.1.1 General	15
7.1.2 Free corrosion under water.....	16
7.1.3 Corrosion at the water/air interface	16
7.1.4 Galvanic cell formation in the presence of external cathodes	16
7.2 High-alloy stainless steels	17
7.3 Hot-dip galvanized steels.....	17
7.4 Copper materials	17
8 Stress-corrosion cracking.....	18
8.1 Unalloyed and low-alloy ferrous materials.....	18
8.2 Austenitic Cr-Ni steels.....	18
8.3 Hot-dip galvanized steels.....	18
8.4 Copper materials	18
9 Corrosion protective measures.....	19
9.1 Unalloyed and low-alloy ferrous materials.....	19
9.1.1 Measures against free corrosion in the presence and in the absence of concentration cells	19
9.1.2 Measures against galvanic cell formation in the presence of external cathodes	19
9.1.3 Measures against stray currents.....	19
9.1.4 Measures against stress corrosion cracking.....	19
9.2 High-alloy stainless steels	19
9.2.1 Measures against pitting and crevice corrosion	19
9.2.2 Measures against stress corrosion cracking.....	19
9.3 Hot-dip galvanized steels.....	20

9.4	Copper materials	20
9.4.1	Measures against free corrosion.....	20
9.4.2	Measures against stray currents.....	20
9.4.3	Measures against stress corrosion cracking	20
	Bibliography.....	21