

# DIN 50929-3:2018-03 (E)

## Corrosion of metals - Corrosion likelihood of metallic materials when subject to corrosion from the outside - Part 3: Buried and underwater pipelines and structural components

---

<b>Contents</b>	<b>Page</b>
Foreword .....	4
1 Scope .....	5
2 Normative references .....	5
3 Terms and definitions.....	6
4 Materials.....	6
5 Explanation of the assessment method.....	7
6 Estimating the likelihood of corrosion of materials in contact with soil.....	8
6.1 Unalloyed and low-alloy ferrous materials.....	8
6.1.1 General .....	8
6.1.2 Free corrosion in the absence of extensive concentration cells.....	8
6.1.3 Free corrosion in the presence of extensive concentration cells.....	11
6.1.4 Assessment of the effect of anodic and cathodic regions in the absence of external cathodes .....	11
6.1.5 Anodic corrosion due to galvanic cell formation in the presence of external cathodes.....	12
6.2 High-alloy stainless steels .....	13
6.3 Hot-dip galvanized steels.....	13
6.4 Copper materials .....	14
7 Estimating the likelihood of corrosion of materials in contact with water .....	15
7.1 Unalloyed and low-alloy ferrous materials.....	15
7.1.1 General .....	15
7.1.2 Free corrosion under water.....	16
7.1.3 Corrosion at the water/air interface.....	16
7.1.4 Galvanic cell formation in the presence of external cathodes .....	16
7.2 High-alloy stainless steels .....	17
7.3 Hot-dip galvanized steels.....	17
7.4 Copper materials .....	17
8 Stress-corrosion cracking.....	18
8.1 Unalloyed and low-alloy ferrous materials.....	18
8.2 Austenitic Cr-Ni steels.....	18
8.3 Hot-dip galvanized steels.....	18
8.4 Copper materials .....	18
9 Corrosion protective measures.....	19
9.1 Unalloyed and low-alloy ferrous materials.....	19
9.1.1 Measures against free corrosion in the presence and in the absence of concentration cells.....	19
9.1.2 Measures against galvanic cell formation in the presence of external cathodes.....	19
9.1.3 Measures against stray currents.....	19
9.1.4 Measures against stress corrosion cracking.....	19
9.2 High-alloy stainless steels .....	19
9.2.1 Measures against pitting and crevice corrosion .....	19
9.2.2 Measures against stress corrosion cracking.....	19
9.3 Hot-dip galvanized steels.....	20

<b>9.4</b>	<b>Copper materials .....</b>	<b>20</b>
<b>9.4.1</b>	<b>Measures against free corrosion.....</b>	<b>20</b>
<b>9.4.2</b>	<b>Measures against stray currents.....</b>	<b>20</b>
<b>9.4.3</b>	<b>Measures against stress corrosion cracking .....</b>	<b>20</b>
	<b>Bibliography .....</b>	<b>21</b>