

ISO 9161:2019 (E)

Uranium dioxide powder — Determination of apparent density and tap density

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Principle
4.1	Apparent density
4.2	Tap density
5	Apparatus
6	Sampling and samples
7	Procedure
7.1	Safety precautions
7.2	Calibration
7.3	Determination of the apparent density
7.4	Determination of tapped density
7.5	Number of determinations
7.6	Quality control
8	Expression of results
8.1	Method of calculation
8.2	Precision
9	Test report

Page count: 7