

# ISO 6101-1:2019-11 (E)

## Rubber - Determination of metal content by atomic absorption spectrometry - Part 1: Determination of zinc content

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Principle .....</b>	<b>2</b>
<b>5</b>	<b>Reagents .....</b>	<b>2</b>
<b>6</b>	<b>Apparatus .....</b>	<b>3</b>
<b>7</b>	<b>Sampling .....</b>	<b>3</b>
<b>8</b>	<b>Procedure .....</b>	<b>4</b>
8.1	Preparation of test portion .....	4
8.2	Preparation of test solution .....	4
8.2.1	Destruction of organic matter .....	4
8.2.2	Dissolution of inorganic matter using hydrochloric acid .....	4
8.2.3	Dissolution of inorganic matter using nitric acid -- Alternative method .....	5
8.3	Preparation of the calibration graph .....	5
8.3.1	Preparation of standard calibration solutions .....	5
8.3.2	Spectrometric measurements .....	5
8.3.3	Plotting the calibration graph .....	6
8.4	Determination .....	6
8.4.1	Spectrometric measurements .....	6
8.4.2	Dilution .....	6
8.4.3	Blank determination .....	6
<b>9</b>	<b>Expression of results .....</b>	<b>6</b>
<b>10</b>	<b>Precision .....</b>	<b>7</b>
<b>11</b>	<b>Test report .....</b>	<b>7</b>
<b>Annex A (informative) Method of standard additions .....</b>		<b>8</b>
<b>Annex B (informative) Precision .....</b>		<b>10</b>
<b>Bibliography .....</b>		<b>11</b>