

ISO 23114:2020-01 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Test method for determining bonding strength of ceramic coatings

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	3
5	Principle	3
6	Apparatus	5
6.1	Testing machine	5
6.2	Data acquisition	5
6.3	Dimension-measuring device	6
6.4	Testing fixture	6
7	Test pieces	7
7.1	Test piece preparation	7
7.1.1	Coating sample	7
7.1.2	Coupling bar	7
7.1.3	Joining of coating sample with coupling bar	7
7.2	Test piece storage	8
7.3	Number of test pieces	8
8	Test procedure	8
8.1	Placement of testing pieces	8
8.2	Test mode and rate	8
8.3	Measurements of the tensile bonding strength	8
8.4	Measurements of the shear bonding strength	9
8.5	Evaluation of the true coating debonded area	9
8.6	Post test	9
9	Calculation of results	10
9.1	Tensile bonding strength of ceramics coating	10
9.2	Shear bonding strength of ceramics coating	10
10	Analysis of precision and uncertainty	10
11	Test report	10
Annex A (informative) Interlaboratory testing		12
Bibliography		13