

# DIN EN 993-10:2020-12 (E)

## Methods of test for dense shaped refractory products - Part 10: Determination of permanent change in dimensions on heating

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Principle .....	6
5	Apparatus .....	6
6	Test pieces .....	7
7	Procedure .....	7
7.1	Drying of the test pieces .....	7
7.2	Measurement of test pieces .....	7
7.2.1	Linear measurement by dial gauge apparatus (Method 1) .....	7
7.2.2	Linear measurement by Vernier callipers (Method 2) .....	7
7.2.3	Volume measurement (Method 3) .....	8
7.3	Mounting of test pieces in the furnace .....	8
7.4	Test temperature .....	8
7.5	Temperature measurement and distribution .....	8
7.6	Heating .....	8
7.7	Maintenance of test temperature .....	9
7.8	Sampling of furnace atmosphere .....	9
7.9	Cooling .....	9
7.10	Measurement of test pieces after firing .....	9
7.10.1	Linear measurement (Methods 1 and 2) .....	9
7.10.2	Volume measurement (Method 3) .....	9
8	Expression of results .....	10
9	Test report .....	10
10	Precision and bias .....	11
10.1	Interlaboratory study .....	11
10.2	Precision data .....	11
10.2.1	Repeatability .....	11
10.2.2	Reproducibility .....	11
10.2.3	Bias .....	11
Table 1 -- Permanent change of dimensions on heating .....		11
Figure 1 -- Length-measuring device (method 1) (side view) .....		12
Figure 2 -- Test piece carrier (method 1) - (plan view) .....		13
Figure 3 -- Measuring points when using Vernier callipers (method 2) .....		13