

DIN EN 993-10:2020-12 (E)

Methods of test for dense shaped refractory products - Part 10: Determination of permanent change in dimensions on heating

Contents		Page
European foreword		3
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Principle	6
5	Apparatus	6
6	Test pieces	7
7	Procedure	7
7.1	Drying of the test pieces	7
7.2	Measurement of test pieces	7
7.2.1	Linear measurement by dial gauge apparatus (Method 1)	7
7.2.2	Linear measurement by Vernier callipers (Method 2)	7
7.2.3	Volume measurement (Method 3)	8
7.3	Mounting of test pieces in the furnace	8
7.4	Test temperature	8
7.5	Temperature measurement and distribution	8
7.6	Heating	8
7.7	Maintenance of test temperature	9
7.8	Sampling of furnace atmosphere	9
7.9	Cooling	9
7.10	Measurement of test pieces after firing	9
7.10.1	Linear measurement (Methods 1 and 2)	9
7.10.2	Volume measurement (Method 3)	9
8	Expression of results	10
9	Test report	10
10	Precision and bias	11
10.1	Interlaboratory study	11
10.2	Precision data	11
10.2.1	Repeatability	11
10.2.2	Reproducibility	11
10.2.3	Bias	11
Table 1 -- Permanent change of dimensions on heating		11
Figure 1 -- Length-measuring device (method 1) (side view)		12
Figure 2 -- Test piece carrier (method 1) - (plan view)		13
Figure 3 -- Measuring points when using Vernier callipers (method 2)		13