

DIN EN 993-10:2020-12 (E)

Methods of test for dense shaped refractory products - Part 10: Determination of permanent change in dimensions on heating

| Contents | | Page |
|--|---|-------------|
| European foreword | | 3 |
| 1 | Scope | 5 |
| 2 | Normative references | 5 |
| 3 | Terms and definitions | 5 |
| 4 | Principle | 6 |
| 5 | Apparatus | 6 |
| 6 | Test pieces | 7 |
| 7 | Procedure | 7 |
| 7.1 | Drying of the test pieces | 7 |
| 7.2 | Measurement of test pieces | 7 |
| 7.2.1 | Linear measurement by dial gauge apparatus (Method 1) | 7 |
| 7.2.2 | Linear measurement by Vernier callipers (Method 2) | 7 |
| 7.2.3 | Volume measurement (Method 3) | 8 |
| 7.3 | Mounting of test pieces in the furnace | 8 |
| 7.4 | Test temperature | 8 |
| 7.5 | Temperature measurement and distribution | 8 |
| 7.6 | Heating | 8 |
| 7.7 | Maintenance of test temperature | 9 |
| 7.8 | Sampling of furnace atmosphere | 9 |
| 7.9 | Cooling | 9 |
| 7.10 | Measurement of test pieces after firing | 9 |
| 7.10.1 | Linear measurement (Methods 1 and 2) | 9 |
| 7.10.2 | Volume measurement (Method 3) | 9 |
| 8 | Expression of results | 10 |
| 9 | Test report | 10 |
| 10 | Precision and bias | 11 |
| 10.1 | Interlaboratory study | 11 |
| 10.2 | Precision data | 11 |
| 10.2.1 | Repeatability | 11 |
| 10.2.2 | Reproducibility | 11 |
| 10.2.3 | Bias | 11 |
| Table 1 -- Permanent change of dimensions on heating | | 11 |
| Figure 1 -- Length-measuring device (method 1) (side view) | | 12 |
| Figure 2 -- Test piece carrier (method 1) - (plan view) | | 13 |
| Figure 3 -- Measuring points when using Vernier callipers (method 2) | | 13 |