

DIN EN ISO 12807:2021-05 (E)

Safe transport of radioactive materials - Leakage testing on packages (ISO 12807:2018)

| Contents | | Page |
|--|---|-------------|
| European foreword | | 4 |
| Foreword | | 5 |
| Introduction | | 6 |
| 1 Scope | | 7 |
| 2 Normative references | | 7 |
| 3 Terms and definitions | | 7 |
| 4 Symbols and units | | 10 |
| 5 Regulatory requirements | | 13 |
| 5.1 | Relevant regulations | 13 |
| 5.2 | Regulatory containment requirements | 13 |
| 6 Procedure for meeting the requirements of this document | | 13 |
| 6.1 | General | 13 |
| 6.2 | Quality management system | 14 |
| 6.3 | Procedure | 14 |
| 6.3.1 | General | 14 |
| 6.3.2 | Determination of permissible activity release rates | 15 |
| 6.3.3 | Determination of standardized leakage rates | 16 |
| 6.3.4 | Determination of permissible test leakage rates for each verification stage | 16 |
| 6.3.5 | Selection of appropriate test methods | 16 |
| 6.3.6 | Performance of test and record of results | 16 |
| 7 Determination of permissible activity release rates | | 16 |
| 7.1 | Step 1: List the radioactive contents, A_i | 16 |
| 7.2 | Step 2: Determine the total releasable activity, RI_T | 16 |
| 7.3 | Step 3: Determine the maximum permissible activity release rates, R | 17 |
| 8 Determination of standardized leakage rates | | 17 |
| 8.1 | General | 17 |
| 8.2 | Step 4: Determine the activity release rate due to permeation, RP | 18 |
| 8.3 | Step 5: Determine the maximum permissible activity release rate due to leakage, RG | 18 |
| 8.4 | Step 6: Determine the activity per unit volume of the containment system medium, C | 18 |
| 8.5 | Step 7: Determine the maximum permissible volumetric leakage rate of the medium, L | 18 |
| 8.6 | Step 8: Determine the maximum permissible equivalent capillary leak diameter, D | 18 |
| 8.7 | Step 9: Determine the permissible standardized leakage rate, Q_{SLR} | 19 |
| 9 Containment-system verification requirements | | 19 |
| 9.1 | Containment-system verification stages | 19 |
| 9.1.1 | General | 19 |
| 9.1.2 | Design verification | 20 |
| 9.1.3 | Fabrication verification | 20 |
| 9.1.4 | Preshipment verification | 20 |
| 9.1.5 | Periodic verification | 21 |
| 9.1.6 | Maintenance verification | 21 |
| 9.2 | Verification requirements | 21 |
| 9.2.1 | General | 21 |
| 9.2.2 | Step 10: Determine permissible test leakage rate for each verification stage, Q_{TDA} , Q_{TDN} , Q_{TF} , Q_{TS} , Q_{TP} and Q_{TM} | 21 |
| 9.2.3 | Step 11: Select appropriate test methods | 21 |

| | | |
|---------------------|---|-----------|
| 10 | Leakage test procedure requirements | 22 |
| 10.1 | General | 22 |
| 10.2 | Step 12: Perform tests and record results | 22 |
| 10.3 | Test sensitivity | 22 |
| 10.4 | Test procedure requirements | 22 |
| | 10.4.1 General | 22 |
| | 10.4.2 Testing | 22 |
| Annex A | (informative) Preferred leakage test methods | 23 |
| Annex B | (informative) Methods of calculation | 37 |
| Annex C | (informative) Conversion tables | 42 |
| Annex D | (informative) Worked examples | 43 |
| Annex E | (informative) Rationale | 78 |
| Bibliography | | 91 |