

# DIN EN ISO 12807:2021-05 (E)

## Safe transport of radioactive materials - Leakage testing on packages (ISO 12807 :2018)

---

Contents	Page
<b>European foreword</b>	4
<b>Foreword</b>	5
<b>Introduction</b>	6
<b>1 Scope</b>	7
<b>2 Normative references</b>	7
<b>3 Terms and definitions</b>	7
<b>4 Symbols and units</b>	10
<b>5 Regulatory requirements</b>	13
5.1 Relevant regulations	13
5.2 Regulatory containment requirements	13
<b>6 Procedure for meeting the requirements of this document</b>	13
6.1 General	13
6.2 Quality management system	14
6.3 Procedure	14
6.3.1 General	14
6.3.2 Determination of permissible activity release rates	15
6.3.3 Determination of standardized leakage rates	16
6.3.4 Determination of permissible test leakage rates for each verification stage	16
6.3.5 Selection of appropriate test methods	16
6.3.6 Performance of test and record of results	16
<b>7 Determination of permissible activity release rates</b>	16
7.1 Step 1: List the radioactive contents, $A_i$	16
7.2 Step 2: Determine the total releasable activity, $R_{IT}$	16
7.3 Step 3: Determine the maximum permissible activity release rates, $R$	17
<b>8 Determination of standardized leakage rates</b>	17
8.1 General	17
8.2 Step 4: Determine the activity release rate due to permeation, $RP$	18
8.3 Step 5: Determine the maximum permissible activity release rate due to leakage, $RG$	18
8.4 Step 6: Determine the activity per unit volume of the containment system medium, $C$	18
8.5 Step 7: Determine the maximum permissible volumetric leakage rate of the medium, $L$	18
8.6 Step 8: Determine the maximum permissible equivalent capillary leak diameter, $D$	18
8.7 Step 9: Determine the permissible standardized leakage rate, $Q_{SLR}$	19
<b>9 Containment-system verification requirements</b>	19
9.1 Containment-system verification stages	19
9.1.1 General	19
9.1.2 Design verification	20
9.1.3 Fabrication verification	20
9.1.4 Preshipment verification	20
9.1.5 Periodic verification	21
9.1.6 Maintenance verification	21
9.2 Verification requirements	21
9.2.1 General	21
9.2.2 Step 10: Determine permissible test leakage rate for each verification stage, $Q_{TDA}$ , $Q_{TDN}$ , $Q_{TF}$ , $Q_{TS}$ , $Q_{TP}$ and $Q_{TM}$	21
9.2.3 Step 11: Select appropriate test methods	21

<b>10</b>	<b>Leakage test procedure requirements .....</b>	<b>22</b>
10.1	General.....	22
10.2	Step 12: Perform tests and record results.....	22
10.3	Test sensitivity.....	22
10.4	Test procedure requirements.....	22
10.4.1	General.....	22
10.4.2	Testing.....	22
	<b>Annex A (informative) Preferred leakage test methods .....</b>	<b>23</b>
	<b>Annex B (informative) Methods of calculation.....</b>	<b>37</b>
	<b>Annex C (informative) Conversion tables .....</b>	<b>42</b>
	<b>Annex D (informative) Worked examples .....</b>	<b>43</b>
	<b>Annex E (informative) Rationale .....</b>	<b>78</b>
	<b>Bibliography .....</b>	<b>91</b>