

ISO 23865:2021 (E)

Non-destructive testing — Ultrasonic testing — General use of full matrix capture/total focusing technique (FMC/TFM) and related technologies

Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Principle of the technique
4.1	General
4.2	Comparison between FMC/TFM and PAUT
5	Requirements for surface condition and couplant
6	Information required prior to testing
6.1	General
6.2	Items to define prior to procedure development
7	Requirements for test personnel
8	Requirements for test equipment
8.1	General
8.2	Instrument
8.3	Probes
8.4	Scanning mechanisms
8.5	Sampling frequency
8.6	Data processing
8.7	Evaluation of TFM indications
9	Benefits of various imaging paths
10	Preparation for testing
10.1	General
10.2	System checking
10.3	Sensitivity correction
10.4	Sensitivity setting
10.5	Grid verification
10.6	Preparation of scanning surfaces
10.7	Couplant
11	Test procedure
12	Data storage
13	Interpretation and analysis of TFM images
13.1	General
13.2	Assessing the quality of TFM images
13.3	Identification of relevant TFM indications
14	Test report
15	Typical influences and compensation mechanisms

Annex A (informative) Comparison of FMC/TFM technique with conventional phased array ultrasonic testing (PAUT)

A.1 Advantages and disadvantages

Annex B (informative) FMC/TFM and alternative acquisition and imaging techniques

- B.1 General**
- B.2 FMC/TFM acquisition and imaging process**
 - B.2.1 FMC acquisition process**
 - B.2.2 TFM imaging process**
- B.3 Alternative acquisition scheme to FMC**
 - B.3.1 General**
 - B.3.2 Acquisition of a subset of the full matrix**
 - B.3.3 Application of delay laws**
 - B.3.4 Application of coded excitation to the array**
- B.4 Reconstruction of multiple imaging paths**
- B.5 Adaptive TFM**

Annex C (informative) Checking of the FMC/TFM setup, ROI and grid

- C.1 Overview**
 - C.1.1 General**
 - C.1.2 Image resolution**
 - C.1.3 Resolution and ROI grid spacing**
- C.2 Amplitude stability verification procedure**
 - C.2.1 Equipment and tools**
 - C.2.2 Verification setup**
 - C.2.3 Verification process**
 - C.2.4 Result calculation**
 - C.2.5 Reporting**

Annex D (informative) Recommended settings and examples of FMC/TFM images

- D.1 Overview**
- D.2 Application on HTHA or similar damages**
 - D.2.1 General – various type of hydrogen damages**
 - D.2.1.1 High-temperature hydrogen attack (HTHA)**
 - D.2.1.2 Other hydrogen induced damages**
 - D.2.2 Specific settings**
 - D.2.3 Probes**
 - D.2.4 Recommended imaging paths**
 - D.2.5 Typical images**
 - D.2.5.1 HTHA images**
 - D.2.5.2 HIC/step wise cracking images**
- D.3 Corrosion testing**
 - D.3.1 Various types of corrosion damages**
 - D.3.2 Specific settings**
 - D.3.3 Probes**
 - D.3.4 Recommended imaging paths**
 - D.3.5 Typical images**
- D.4 SCC testing**
 - D.4.1 General**
 - D.4.2 Specific settings**
 - D.4.2.1 Scanning surfaces and geometry**
 - D.4.2.2 Calibration**
 - D.4.2.3 Reference levels**
 - D.4.2.4 Sensitivity**
 - D.4.3 Probes**
 - D.4.4 Recommended imaging paths**
 - D.4.5 Example images**
- D.5 Testing of casting and forging**
 - D.5.1 General**
 - D.5.2 Specific settings**
 - D.5.3 Probes**
 - D.5.4 Recommended imaging paths**
 - D.5.5 Typical images**