

DIN EN ISO 3613:2021-08 (E)

Metallic and other inorganic coatings - Chromate conversion coatings on zinc, cadmium, aluminium-zinc alloys and zinc-aluminium alloys - Test methods (ISO 3613:2021)

Contents	Page
European foreword	3
Foreword	4
Introduction	5
1 Scope	6
2 Normative references	6
3 Terms and definitions	6
4 Reagents	7
5 Apparatus	8
6 Test methods	9
6.1 General	9
6.2 Test for the presence of a colourless chromate coating on zinc	9
6.3 Test for the presence of a colourless chromate coating on zinc and cadmium	9
6.4 Test for the presence of a colourless chromate coating on zinc-aluminium (mass fraction of aluminium: 5 %) alloys	10
6.5 Test for the presence of hexavalent chromium in both colourless and coloured chromate coatings	10
6.5.1 General	10
6.5.2 Test method employing test solution C 1	10
6.5.3 Test method employing alternative test solution C 2 (destructive)	10
6.5.4 Expression of results	12
6.5.5 Calibration of spectrophotometer	12
6.6 Determination of hexavalent chromium content of coloured chromate coatings	13
6.6.1 Preparation of calibration graph	13
6.6.2 Blank test	13
6.6.3 Determination	13
6.6.4 Expression of results	13
6.7 Determination of total chromium content of coloured chromate coatings	14
6.7.1 Preparation of calibration graph	14
6.7.2 Blank test	14
6.7.3 Determination	14
6.7.4 Expression of results	14
6.8 Determination of mass per unit area of both colourless and coloured chromate coatings by gravimetric method	14
6.9 Test for adhesion by abrasion	14
6.10 Quality evaluation test of chromate layers on zinc and cadmium surfaces	15
7 Test report	15
Bibliography	16