

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms, definitions, symbols and abbreviated terms
3.1	Terms and definitions
3.2	Symbols and abbreviated terms
4	Experimental boundary conditions with respect to the sample
5	Experimental boundary conditions with respect to the measurement
6	Model-correlated boundary conditions of the simulation
7	Basic models
7.1	General
7.2	Bulk material (case 1 of application)
7.3	Transparent single layer (case 2 of application)
7.4	Semi-transparent single layer (case 3 of application)
7.5	Multiple layers and periodic layers (case 4 of application)
7.6	Effective materials (case 5 of application)
8	Raw data
9	Verification of correct adjustment of the device
9.1	Straight line measurement
9.2	Simple measurement of angles
9.2.1	Measurement on a known sample, e.g. SiO <sub>2</sub> /Si, with fitting of the angle of incidence
9.2.2	Measurement of the Brewster's angle of water, of a solvent or of technical glass
10	Verification of the device regarding correct calibration
11	Test report
Annex A	(informative) Mathematical and physical principles of ellipsometry
A.1	Optical parameters
A.2	Optical material constants and function
A.3	Dielectric constants and function
A.4	Relationship between complex refractive index $N$ and dielectric function $\epsilon$
A.5	Definition of the pseudo-dielectric function
A.6	Interface parameters
A.7	Quality function between model-based simulated (mod.) and experimentally determined (exp.) ellipsometric transfer quantities
A.8	Jones vectors and Jones matrices
A.9	Stokes vectors and Mueller matrices