

# ISO 19318:2021 (E)

## Surface chemical analysis — X-ray photoelectron spectroscopy — Reporting of methods used for charge control and charge correction

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Symbols and abbreviated terms
5	Apparatus
6	Calibration of binding-energy scale
7	Reporting of information related to charge control
7.1	General
7.2	Information about specimen
7.2.1	Specimen form
7.2.2	Specimen dimensions
7.2.3	Specimen mounting methods
7.2.4	Specimen treatment prior to or during analysis
7.3	Instrument and operating conditions
7.4	General method for charge control
7.5	Reasons for needing charge control and for choosing the particular method for charge control
7.6	Values of experimental parameters
7.7	Information on the effectiveness of the method of charge control
7.7.1	Adequacy of charge control
7.7.2	Damage assessment
8	Reporting of method(s) used for charge correction and the value of that correction
8.1	General
8.2	Approach
8.3	Value of correction energy
Annex A	(informative) Description of methods of charge control and charge correction
A.1	General
A.2	Methods of charge control
A.2.1	Damage caution
A.2.2	Electron flood gun[15-18]
A.2.3	Ultraviolet flood lamp[21]
A.2.4	Specimen heating
A.2.5	Electrical connection
A.2.5.1	Grounding and enhanced conduction path
A.2.5.2	Isolation from ground
A.2.5.3	Biasing
A.2.6	Low-energy ion source
A.3	Methods of charge correction
A.3.1	General
A.3.2	Differential charging
A.3.3	Adventitious-hydrocarbon referencing [11,15,21,29-33]

- A.3.4 Gold deposition[15,16,35-38]**
- A.3.5 Implantation with inert gases[40]**
- A.3.6 Internal referencing**
- A.3.7 Substrate referencing**
- A.4 Bias referencing[27]**
- A.5 Auger parameter measurements[47-49]**

**Page count: 14**