

# ISO 10111:2000-06 (E)

## Metallic and other inorganic coatings - Measurement of mass per unit area - Review of gravimetric and chemical analysis methods

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b> <b>Scope</b> .....		<b>1</b>
<b>2</b> <b>Normative references</b> .....		<b>2</b>
<b>3</b> <b>Terms and definitions</b> .....		<b>2</b>
<b>4</b> <b>Principle</b> .....		<b>3</b>
<b>5</b> <b>Special equipment</b> .....		<b>3</b>
<b>6</b> <b>Preparation of test specimen</b> .....		<b>3</b>
<b>7</b> <b>Measurement of coated area</b> .....		<b>4</b>
<b>8</b> <b>Determination of mass of coating by chemical analysis</b> .....		<b>4</b>
<b>9</b> <b>Gravimetric determination of mass of coating</b> .....		<b>5</b>
<b>10</b> <b>Calculations</b> .....		<b>6</b>
<b>Annex A (normative) Reagents for selective dissolution of metal layers</b> .....		<b>7</b>
<b>Bibliography</b> .....		<b>13</b>