

# ISO 24417:2022-09 (E)

## Surface chemical analysis - Analysis of metallic nanolayers on iron based substrates by glow-discharge optical-emission spectrometry

---

<b>Contents</b>		<b>Page</b>
	Foreword.....	v
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Principle</b> .....	<b>1</b>
<b>5</b>	<b>Apparatus</b> .....	<b>2</b>
5.1	Glow discharge optical emission spectrometer.....	2
5.1.1	General.....	2
5.1.2	Selection of spectral lines.....	2
5.1.3	Selection of glow discharge source type.....	2
<b>6</b>	<b>Adjusting the glow discharge spectrometer system settings</b> .....	<b>3</b>
6.1	General.....	3
6.2	Setting the parameters of a DC source.....	4
6.2.1	Constant applied current and voltage.....	4
6.2.2	Constant applied current and pressure.....	5
6.2.3	Constant voltage and pressure.....	5
6.3	Setting the discharge parameters of an RF source.....	6
6.3.1	General.....	6
6.3.2	Constant applied power and pressure.....	6
6.3.3	Constant applied power and DC bias voltage.....	6
6.3.4	Constant effective power and effective RF voltage.....	7
6.4	Minimum performance requirements.....	7
6.4.1	General.....	7
6.4.2	Control of lamp cleanliness and start-up performance.....	7
6.4.3	Minimum repeatability.....	9
6.4.4	Detection limit.....	9
<b>7</b>	<b>Sampling</b> .....	<b>11</b>
<b>8</b>	<b>Calibration</b> .....	<b>11</b>
8.1	General.....	11
8.2	Calibration samples.....	11
8.2.1	General.....	11
8.2.2	Low alloy iron or steel samples.....	12
8.2.3	Stainless steel samples.....	12
8.2.4	Nickel alloy samples.....	12
8.2.5	Titanium alloy samples.....	12
8.2.6	Aluminium alloy samples.....	12
8.2.7	High oxygen samples.....	12
8.2.8	High carbon samples.....	12
8.2.9	High purity copper sample.....	12
8.3	Validation samples.....	13
8.4	Determination of the sputtering rate of calibration samples.....	13
8.5	Emission intensity measurements of calibration samples.....	14
8.6	Calculation of calibration equations.....	14
8.7	Validation using reference materials.....	14
8.7.1	General.....	14
8.7.2	Checking analytical accuracy using bulk reference materials.....	15
8.7.3	Checking analytical accuracy using surface layer reference materials.....	15

8.8	Verification and drift correction .....	15
<b>9</b>	<b>Analysis of test specimens</b> .....	<b>16</b>
9.1	Adjusting discharge parameters .....	16
9.2	Setting of measuring time and data acquisition rate.....	16
9.3	Quantifying depth profiles of test specimens.....	16
<b>10</b>	<b>Expression of results</b> .....	<b>17</b>
10.1	Expression of quantitative depth profile .....	17
10.2	Determination of total coating mass per unit area (coating areic mass) .....	17
<b>11</b>	<b>Precision</b> .....	<b>17</b>
<b>12</b>	<b>Test report</b> .....	<b>18</b>
<b>Annex A</b> (normative)	<b>Calculation of calibration constants and quantitative evaluation of depth profiles</b> .....	<b>19</b>
<b>Annex B</b> (informative)	<b>Suggestions concerning suitable spectral lines</b> .....	<b>31</b>
<b>Annex C</b> (informative)	<b>Additional information on international cooperative tests</b> .....	<b>32</b>
<b>Bibliography</b>	.....	<b>35</b>