

# DIN EN ISO 6507-1:2024-01 (E)

## Metallic materials - Vickers hardness test - Part 1: Test method (ISO 6507-1:2023)

<b>Contents</b>	<b>Page</b>
European foreword .....	3
Foreword.....	4
<b>1 Scope</b> .....	<b>5</b>
<b>2 Normative references</b> .....	<b>5</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Symbols and designations</b> .....	<b>6</b>
4.1 Symbols and designations used in this document.....	6
4.2 Designation of hardness number.....	7
<b>5 Principle</b> .....	<b>7</b>
<b>6 Testing machine</b> .....	<b>8</b>
6.1 Testing machine.....	8
6.2 Indenter.....	8
6.3 Diagonal measuring system.....	8
<b>7 Test piece</b> .....	<b>9</b>
7.1 Test surface.....	9
7.2 Preparation.....	9
7.3 Thickness.....	9
7.4 Tests on curved surfaces.....	9
7.5 Support of unstable test pieces.....	9
7.6 Metallic and other inorganic coatings.....	9
<b>8 Procedure</b> .....	<b>10</b>
8.1 Test temperature.....	10
8.2 Test force.....	10
8.3 Periodic verification.....	10
8.4 Test piece support and orientation.....	10
8.5 Focus on test surface.....	11
8.6 Test force application.....	11
8.7 Prevention of the effect of shock or vibration.....	11
8.8 Minimum distance between adjacent indentations.....	11
8.9 Measurement of the diagonal length.....	12
8.10 Calculation of hardness value.....	12
<b>9 Uncertainty of the results</b> .....	<b>12</b>
<b>10 Test report</b> .....	<b>13</b>
<b>Annex A (normative) Minimum thickness of the test piece in relation to the test force and hardness</b> .....	<b>14</b>
<b>Annex B (normative) Tables of correction factors for use in tests made on curved surfaces</b> .....	<b>16</b>
<b>Annex C (normative) Procedure for periodic checking of the testing machine, diagonal measuring system and indenter by the user</b> .....	<b>20</b>
<b>Annex D (informative) Uncertainty of the measured hardness values</b> .....	<b>22</b>
<b>Annex E (informative) Vickers hardness measurement traceability</b> .....	<b>29</b>
<b>Annex F (informative) CCM — Working group on hardness</b> .....	<b>33</b>
<b>Annex G (informative) Adjustment of Köhler illumination systems</b> .....	<b>34</b>
<b>Annex H (normative) Determining the Vickers hardness of metallic and other inorganic coatings</b> .....	<b>35</b>
<b>Bibliography</b> .....	<b>39</b>