

# ISO 3882:2024-01 (E)

## Metallic and other inorganic coatings - Review of methods of measurement of thickness

---

<b>Contents</b>		Page
<b>Foreword</b>		iv
<b>Introduction</b>		v
<b>1 Scope</b>		1
<b>2 Normative references</b>		1
<b>3 Terms and definitions</b>		1
<b>4 Overview</b>		1
<b>5 Non-destructive methods</b>		2
5.1	Split beam microscope (light section) method, ISO 2128	2
5.2	Magnetic methods, ISO 2178 and ISO 2361	2
5.3	Eddy current methods, ISO 2360 and ISO 21968	2
5.4	X-ray spectrometric method, ISO 3497	3
5.5	Beta backscatter method, ISO 3543	3
<b>6 Destructive methods</b>		4
6.1	Microscopical (optical) method, ISO 1463	4
6.2	Fizeau multiple-beam interferometry method, ISO 3868	4
6.3	Profilometric method, ISO 4518	4
6.4	Scanning electron microscope method, ISO 9220	4
6.5	Dissolution methods	4
6.5.1	Coulometric method, ISO 2177	4
6.5.2	Gravimetric (strip and weigh) method, ISO 10111	5
6.5.3	Gravimetric (analytical) method, ISO 10111	5
<b>Annex A (informative) Typical measuring application and range</b>		6
<b>Bibliography</b>		9