

ISO 18118:2024-02 (E)

Surface chemical analysis - Auger electron spectroscopy and X-ray photoelectron spectroscopy - Guide to the use of experimentally determined relative sensitivity factors for the quantitative analysis of homogeneous materials

| Contents | | Page |
|--|--|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Symbols and abbreviated terms | 4 |
| 5 | General information | 5 |
| 6 | Measurement conditions | 6 |
| 6.1 | General | 6 |
| 6.2 | Excitation source | 7 |
| 6.3 | Energy resolution | 7 |
| 6.4 | Energy step and scan rate | 7 |
| 6.5 | Signal intensity | 7 |
| 6.6 | Gain and time constant (for AES instruments with analogue detection systems) | 7 |
| 6.7 | Modulation to generate a derivative spectrum | 7 |
| 7 | Data-analysis procedures | 7 |
| 8 | Spectrometer response function | 8 |
| 9 | Determination of chemical composition using relative sensitivity factors | 8 |
| 9.1 | Calculation of chemical composition | 8 |
| 9.1.1 | General | 8 |
| 9.1.2 | Composition determined from elemental relative sensitivity factors | 9 |
| 9.1.3 | Composition determined from atomic relative sensitivity factors or average matrix relative sensitivity factors | 9 |
| 9.2 | Uncertainties in calculated compositions | 9 |
| Annex A (informative) Formulae for relative sensitivity factors | | 10 |
| Annex B (informative) Information on uncertainty of the analytical results | | 16 |
| Bibliography | | 19 |