

DIN EN ISO 4259-4:2025-09 (E)

Petroleum and related products - Precision of measurement methods and results - Part 4: Use of statistical control charts to validate 'in-statistical-control' status for the execution of a standard test method in a single laboratory (ISO 4259-4:2021, Corrected version 2023-10)

| Contents | Page |
|---|-------------|
| Foreword | iv |
| Introduction | v |
| 1 Scope | 1 |
| 2 Normative references | 1 |
| 3 Terms, definitions, symbols and abbreviated terms | 1 |
| 3.1 Specific terms and definitions..... | 2 |
| 3.2 Symbols and abbreviated terms..... | 2 |
| 4 Statistical control in the execution of a standard test method by a laboratory | 3 |
| 4.1 General..... | 3 |
| 4.2 Control chart description..... | 4 |
| 4.2.1 General..... | 4 |
| 4.2.2 I- and MR-charts..... | 4 |
| 4.2.3 I-chart sensitivity enhancement strategy..... | 4 |
| 4.2.4 In-statistical-control conditions..... | 5 |
| 4.3 Control chart work process..... | 5 |
| 4.3.1 General..... | 5 |
| 4.3.2 Stage 1 of control chart work process..... | 5 |
| 4.3.3 Stage 2 of control chart work process..... | 9 |
| 4.4 QC material batch change transition..... | 11 |
| 4.4.1 General..... | 11 |
| 4.4.2 Procedure 1, concurrent testing..... | 12 |
| 4.4.3 Procedure 2, Q-chart..... | 12 |
| 4.4.4 Procedure 3, dynamically updated I-chart with EWMA..... | 12 |
| 5 Guidance for insufficient variation or non-normal data | 13 |
| 5.1 General requirement..... | 13 |
| 5.2 How to deal with insufficient variation or non-normal data..... | 13 |
| 5.2.1 Insufficient variation..... | 13 |
| 5.2.2 Non-normal data..... | 14 |
| Annex A (informative) Details of the control chart work process | 15 |
| Annex B (normative) Check procedures | 34 |
| Bibliography | 36 |