

ISO 11505:2025-06 (E)

Surface chemical analysis - General procedures for quantitative compositional depth profiling by glow discharge optical emission spectrometry

Contents

Page

Foreword.....	v
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	1
4 Principle.....	1
5 Apparatus.....	2
5.1 Glow discharge optical emission spectrometer.....	2
5.1.1 General.....	2
5.1.2 Selection of spectral lines.....	2
5.1.3 Selection of glow discharge source type.....	2
6 Adjusting the glow discharge spectrometer system settings.....	3
6.1 General.....	3
6.2 Setting the discharge parameters of a DC source.....	4
6.2.1 Constant applied current and voltage.....	4
6.2.2 Constant applied current and pressure.....	5
6.2.3 Constant applied voltage and pressure.....	5
6.3 Setting the discharge parameters of an RF source.....	6
6.3.1 Constant applied power and pressure.....	6
6.3.2 Constant applied power and DC bias voltage.....	6
6.3.3 Constant effective power and RF voltage.....	7
6.4 Minimum performance requirements.....	7
6.4.1 General.....	7
6.4.2 Control of lamp cleanliness and start-up performance.....	7
6.4.3 Minimum repeatability.....	9
6.4.4 Detection limit.....	9
7 Sampling.....	11
8 Calibration.....	11
8.1 General.....	11
8.2 Calibration specimens.....	11
8.2.1 General.....	11
8.2.2 Low-alloy iron or steel specimens.....	12
8.2.3 Stainless-steel specimens.....	12
8.2.4 High-oxygen specimens.....	12
8.2.5 High-carbon specimens.....	12
8.2.6 High-nitrogen specimens.....	12
8.2.7 High-purity copper specimens.....	12
8.2.8 High-purity zinc specimens.....	13
8.3 Validation specimens.....	13
8.4 Determination of the sputtering rate of calibration and validation specimens.....	13
8.5 Emission intensity measurements of calibration specimens.....	14
8.6 Calculation of calibration formulae.....	14
8.7 Validation of the calibration.....	14
8.7.1 General.....	14
8.7.2 Checking analytical accuracy using bulk reference materials.....	15
8.7.3 Checking analytical accuracy using surface layer reference materials.....	15
8.8 Verification and drift correction.....	15

9	Analysis of test specimens	16
9.1	Adjusting discharge parameters.....	16
9.2	Setting of measuring time and data acquisition rate.....	16
9.3	Quantifying depth profiles of test specimens.....	16
10	Expression of results	16
10.1	Expression of quantitative depth profile.....	16
10.2	Determination of total coating mass per unit area.....	17
10.3	Determination of average mass fractions.....	18
11	Precision	18
12	Test report	18
Annex A (normative)	Calculation of calibration constants and quantitative evaluation of depth profiles	19
Annex B (informative)	Suggested spectral lines for determination of given elements	32
Bibliography	34