

DIN EN 15365:2026-02 (E)

Advanced technical ceramics - Mechanical properties of ceramic fibres at high temperature in a non-reactive environment - Determination of creep behaviour by the cold grip method

Contents		Page
European foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	4
4	Principle	7
5	Significance and use	9
6	Apparatus	9
6.1	Test installations	9
6.2	Load train	9
6.3	Test chamber	9
6.4	Set-up for heating	10
6.5	Temperature measurement	10
6.6	Control of deformation	10
6.7	Data recording system	10
6.8	Determination of fibre cross-sectional area	10
7	Test specimens	10
7.1	Test specimen preparation	10
7.2	Number of test specimens	12
8	Test procedures	12
8.1	Determination of the temperature profile in the furnace	12
8.2	Test set-up: Determination of the temperature profile and of the different lengths of each temperature zone in the furnace	12
8.3	Test set-up: Loading considerations	12
8.4	Test technique	12
8.4.1	Specimen mounting	12
8.4.2	Setting of an inert environment	12
8.4.3	Heating of the test specimen	13
8.4.4	Measurements	13
8.4.5	Monitoring of temperature stability	14
8.5	Test validity	14
9	Calculation of results	14
9.1	Creep stress	14
9.2	Creep strain at time t	15
9.2.1	Reading of the longitudinal deformation	15
9.2.2	Calculation of the deformation due to the creep	15
9.2.3	Drawing of the creep curve	15
9.2.4	Creep strain at rupture	15
9.2.5	Creep rupture time	15
9.2.6	Creep strain rate curve	15

10	Test report	16
Bibliography		17