

# DIN EN 15365:2026-02 (E)

## Advanced technical ceramics - Mechanical properties of ceramic fibres at high temperature in a non-reactive environment - Determination of creep behaviour by the cold grip method

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Terms and definitions .....	4
4	Principle .....	7
5	Significance and use .....	9
6	Apparatus .....	9
6.1	Test installations .....	9
6.2	Load train .....	9
6.3	Test chamber .....	9
6.4	Set-up for heating .....	10
6.5	Temperature measurement .....	10
6.6	Control of deformation .....	10
6.7	Data recording system .....	10
6.8	Determination of fibre cross-sectional area .....	10
7	Test specimens .....	10
7.1	Test specimen preparation .....	10
7.2	Number of test specimens .....	12
8	Test procedures .....	12
8.1	Determination of the temperature profile in the furnace .....	12
8.2	Test set-up: Determination of the temperature profile and of the different lengths of each temperature zone in the furnace .....	12
8.3	Test set-up: Loading considerations .....	12
8.4	Test technique .....	12
8.4.1	Specimen mounting .....	12
8.4.2	Setting of an inert environment .....	12
8.4.3	Heating of the test specimen .....	13
8.4.4	Measurements .....	13
8.4.5	Monitoring of temperature stability .....	14
8.5	Test validity .....	14
9	Calculation of results .....	14
9.1	Creep stress .....	14
9.2	Creep strain at time t .....	15
9.2.1	Reading of the longitudinal deformation .....	15
9.2.2	Calculation of the deformation due to the creep .....	15
9.2.3	Drawing of the creep curve .....	15
9.2.4	Creep strain at rupture .....	15
9.2.5	Creep rupture time .....	15
9.2.6	Creep strain rate curve .....	15

<b>10</b>	<b>Test report .....</b>	<b>16</b>
<b>Bibliography .....</b>		<b>17</b>