

ISO 25086-1:2026-01 (E)

Textiles - Determination of the snagging resistance of fabrics - Part 1: Mace (spiked ball) test method

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Principle		1
5 Apparatus		2
6 Pre-treatment of fabric		4
7 Atmosphere for conditioning and testing		4
8 Preparation of test specimens		4
9 Procedure		5
9.1 Mounting of the felt.....		5
9.2 Checking and adjustment of the mace (spiked ball).....		5
9.3 Setting of the testing time.....		6
9.4 Test specimen mounting.....		6
9.5 Testing running.....		6
10 Assessment of snagging		6
11 Test report		7
Bibliography		9