

# ISO 13909-3:2001-12 (E)

## Hard coal and coke - Mechanical sampling - Part 3: Coal; Sampling from stationary lots

---

<b>Contents</b>		<b>Page</b>
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Establishing a sampling scheme .....	2
5	Methods of sampling from wagons, barges and ships .....	9
6	Methods of sampling from stockpiles .....	11
7	Sampling equipment -- mechanical auger .....	12
8	Handling and storage of samples .....	13
9	Sample preparation .....	14
10	Minimization of bias .....	14
11	Verification .....	15
Annex A Examples of calculations of the number of sub-lots and number of increments per sub-lot (sampling from stationary lots) .....		16
Bibliography .....		19