

ISO 7539-9:2003-04 (E)

Corrosion of metals and alloys - Stress corrosion testing - Part 9: Preparation and use of pre-cracked specimens for tests under rising load or rising displacement

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Principle	2
5	Specimens	3
6	Initiation and propagation of fatigue cracks	16
7	Procedure	18
8	Test report	23
Annex A (informative) Determination of a suitable displacement rate for determining KISCC from constant displacement rate tests		24
Annex B (informative) Determination of crack growth velocity		25
Annex C (informative) Information on indirect methods for measuring crack length		26