

ISO 17636:2003-09 (E)

Non-destructive testing of welds - Radiographic testing of fusion-welded joints

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviations	2
5	Classification of radiographic techniques	3
6	General	3
6.1	Protection against ionizing radiation	3
6.2	Surface preparation and stage of manufacture	3
6.3	Location of the weld in the radiograph	3
6.4	Identification of radiographs	3
6.5	Marking	3
6.6	Overlap of films	4
6.7	Types and positions of image quality indicators (IQI)	4
6.8	Evaluation of image quality	4
6.9	Minimum image quality values	5
6.10	Personnel qualification	5
7	Recommended techniques for making radiographs	5
7.1	Test arrangements	5
7.2	Choice of tube voltage and radiation source	15
7.3	Film systems and screens	17
7.4	Alignment of beam	19
7.5	Reduction of scattered radiation	19
7.6	Source-to-object distance	19
7.7	Maximum area for a single exposure	21
7.8	Density of radiograph	22
7.9	Processing	22
7.10	Film viewing conditions	22
8	Test report	22
Annex A (normative) Minimum image quality values for ferrous materials		24
Annex B (informative) Recommended number of exposures for acceptable testing of a circumferential butt weld		30
Bibliography		35