

ISO 7476:2003-11 (E)

Nuclear fuel technology - Determination of uranium in uranyl nitrate solutions of nuclear grade quality - Gravimetric method

Contents		Page
1	Scope	1
2	Normative references	1
3	Principle	1
4	Interferences	1
5	Reagents	1
6	Apparatus	2
7	Procedure	2
8	Expression of results	3
9	Procedure validation and quality control	5
10	Repeatability	5
11	Accuracy and bias	5
12	Test report	5
Annex A (normative) Gravimetric conversion factors for non-volatile impurities		6