

ISO 6962:2004-07 (E)

Nuclear energy - Standard method for testing the long-term alpha irradiation stability of matrices for solidification of high-level radioactive waste

| Contents | | Page |
|--------------------|---|-------------|
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Principle | 2 |
| 5 | Test Method | 2 |
| 6 | Sample composition | 3 |
| 7 | Sample preparation | 3 |
| 8 | Measurements before storage | 3 |
| 9 | Storage | 3 |
| 10 | Measurements during and after storage | 4 |
| 11 | Test report | 5 |
| Bibliography | | 8 |