

# DIN 51309:2005-12 (E)

## Materials testing machines - Calibration of static torque measuring devices

---

<b>Contents</b>		<b>Page</b>
Foreword .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Symbols .....</b>	<b>5</b>
<b>4</b>	<b>Characteristics of the torque measuring instrument .....</b>	<b>7</b>
4.1	Description and marking of the torque measuring instrument .....	7
4.2	Inducing the torque .....	7
4.3	Measurement of the torque by deformation .....	7
<b>5</b>	<b>Calibration of the torque measuring instrument .....</b>	<b>7</b>
5.1	General .....	7
5.1.1	Requirements .....	7
5.1.2	Overload check .....	8
5.2	Resolution of the display unit .....	8
5.2.1	Scale indication .....	8
5.2.2	Numeric display .....	8
5.2.3	Indication fluctuation .....	8
5.2.4	Units .....	8
5.2.5	Measurement range initial value .....	8
5.3	Preparation of the calibration .....	8
5.3.1	Display unit .....	8
5.3.2	Temperature equalization .....	9
5.3.3	Transducer zero value $I_s$ .....	9
5.3.4	Installation direction, transducer connection .....	9
5.4	Carrying out the calibration .....	9
5.4.1	Scope of the calibration and procedure .....	9
5.4.2	Preloading .....	10
5.4.3	Installation position .....	10
5.4.4	Carrying out the calibration .....	10
5.4.5	Loading conditions .....	11
5.4.6	Displayed value corrected for the zero value $X_j(MK)$ .....	11
5.4.7	Evaluation of the torque measuring instruments .....	11
5.4.8	Short-time creeping .....	14
<b>6</b>	<b>Classification of the torque measuring instrument .....</b>	<b>14</b>
6.1	Classification principle .....	14
6.2	Measurement range initial value and classification criteria .....	14
6.2.1	Measurement range initial value .....	14
6.2.2	Classification criteria .....	14
6.3	Calibration certificate and recalibration .....	15
6.3.1	Calibration certificate .....	15
6.3.2	Recalibration .....	16
<b>7</b>	<b>Standard designation .....</b>	<b>16</b>
Annex A (normative)	Application of calibrated torque measuring instruments .....	17

<b>Annex B (informative) Recommended dimensions for torque transducers, including couplings for their adaptation in torque calibrators .....</b>	<b>18</b>
<b>Annex C (informative) Determination of the relative expanded measurement uncertainty W for the calibration of torque measuring instruments .....</b>	<b>19</b>
<b>C.1 Determination of the measurement uncertainty of the interpolated calibration result for the calibration of torque measuring instruments .....</b>	<b>19</b>
<b>C.1.1 Model .....</b>	<b>19</b>
<b>C.1.2 Measurement uncertainty budget .....</b>	<b>20</b>
<b>Annex D (informative) Calibration procedure .....</b>	<b>24</b>
<b>Annex E (informative) Features for measurement of vibratory torque .....</b>	<b>25</b>
<b>Bibliography .....</b>	<b>27</b>
<b>List of figures Figure B.1 .....</b>	<b>18</b>
<b>Figure D.1 -- Example of the preloadings and measurement series for the classes 0,05 and 0,1 .....</b>	<b>24</b>
<b>Figure D.2 -- Example of the preloadings and measurement series of square drive transducers for the classes 0,2 and 0,5 .....</b>	<b>24</b>
<b>Figure D.3 -- Example of the preloadings and measurement series of square drive transducers for the classes 1 to 5 .....</b>	<b>24</b>
<b>Figure E.1 -- Interpolation deviations for clockwise and anti-clockwise torque, related to the corresponding zero points (here and in the following, filled symbols signify: increasing value of the torque; blank symbols: decreasing value) .....</b>	<b>25</b>
<b>Figure E.2 -- Interpolation deviations for alternating torque with integrated contours for clockwise and anti-clockwise torque, related to the mean value of the associated zero points .....</b>	<b>26</b>
<b>Figure E.3 -- Range of the interpolation deviation (thick line) for an alternating torque transducer with unknown history .....</b>	<b>26</b>
<b>List of tables Table 1 -- Symbols, units and designation .....</b>	<b>5</b>
<b>Table 2 -- Number of series of measurements required .....</b>	<b>10</b>
<b>Table 3 -- Classification characteristics of the torque measuring instruments .....</b>	<b>15</b>
<b>Table B.1</b>	<b>18</b>
<b>Table C.1 -- Distribution functions for the calculation of the relative standard deviations for the parameters calculated from the ranges determined from experiment .....</b>	<b>20</b>
<b>Table C.2 -- Example for the tabular calculation of the relative standard measurement uncertainty w for torque measuring instruments for static torques .....</b>	<b>23</b>