

ISO 21687:2007-03 (E)

Carbonaceous materials used in the production of aluminium - Determination of density by gas pycnometry (volumetric) using helium as the analysis gas - Solid materials

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Apparatus and materials	2
6	Sampling, sample preparation and drying	2
7	Procedure	3
8	Calculation	3
9	Precision	4
10	Test report	5
Bibliography		6