

DIN EN ISO 5398-4:2007-10 (E)

Leather - Chemical determination of chromic oxide content - Part 4: Quantification by inductively coupled plasma - optical emission spectrometer (ICP-OES) (ISO 5398-4:2007)

Contents		Page
Foreword.....		3
Introduction		4
1 Scope		5
2 Normative references		5
3 Terms and definitions		5
4 Principle.....		6
5 Sampling and sample preparation		6
6 Reagents.....		6
6.1 Wet oxidation method		6
6.2 ICP-OES		6
7 Apparatus		6
8 Methods		7
8.1 Preparation of analytical solution.....		7
8.2 Measurement of the aqueous solution.....		7
9 Calculation and expression of results.....		8
10 Test report		9
Annex A (informative) Determination of water and other volatile matter		10