

ISO 15463:2003-12 (E)

Petroleum and natural gas industries - Field inspection of new casing, tubing and plain-end drill pipe

Contents		Page
Foreword		vi
Introduction		vii
1	Scope	1
2	Conformance	1
2.1	Normative references	1
2.2	Units of measurement	1
2.3	Tables and figures	2
3	Normative references	2
4	Terms, definitions, symbols and abbreviated terms	2
4.1	Terms and definitions	2
4.2	Symbols and abbreviated terms	13
5	Application	15
5.1	Basis for inspection	15
5.2	Applicability of inspections	15
5.3	Repeatability of results	15
5.4	Consequences of variability	15
6	Ordering information	16
7	Quality assurance	16
8	Qualification of inspection personnel	17
8.1	General	17
8.2	Written procedure	17
8.3	Qualification of inspection personnel	17
8.4	Training programs	18
8.5	Examinations	18
8.6	Experience	18
8.7	Requalification	18
8.8	Documentation	18
8.9	NDT personnel certification	19
9	General inspection procedures	19
9.1	General	19
9.2	Documents at job site	19
9.3	Pre-inspection procedures	19
9.4	Records and notification	19
9.5	Post-inspection procedures	20
9.6	Job site checklist	21
9.7	Documentation	21
10	Acceptance criteria, disposition and responsibility	21
10.1	General	21
10.2	Basis for acceptance	21
10.3	Responsibility for Rejections	21

11	Visual and dimensional inspection	22
11.1	General	22
11.2	Application	22
11.3	Drift mandrels	22
11.4	Precision callipers (micrometer, vernier calliper or dial calliper)	22
11.5	Length and diameter-measuring devices (steel rules, steel length or diameter-measuring tapes, and other non-adjustable measuring devices)	22
11.6	Depth gauges	22
11.7	External surface illumination	23
11.8	Internal surface illumination	23
11.9	Full-length visual inspection (FLVI) of new OCTG	24
11.10	Outside diameter verification	24
11.11	Straightness	24
11.12	Drift testing	25
11.13	Visual thread inspection (VTI)	26
12	Hardness testing	29
12.1	General	29
12.2	Application	29
12.3	Equipment	30
12.4	Calibration	30
12.5	Standardization	30
12.6	Procedures	31
13	Magnetic particle inspection (MPI)	31
13.1	General	31
13.2	Application	32
13.3	Equipment and materials	32
13.3.1	Internal conductors	32
13.4	Magnetic particles	33
13.5	Illumination equipment and optical aids	33
13.6	General procedures	34
13.7	Calibration	34
13.8	Standardization	35
13.9	Periodic checks	35
13.10	End area inspection (SEA)	36
13.11	Inspection of unattached couplings (UCMPI)	37
13.12	Full-length magnetic particle inspection (FLMPI)	38
14	Electromagnetic inspection (EMI)	38
14.1	General	38
14.2	Equipment	39
14.3	Application	39
14.4	Calibration	39
14.5	Standardization	40
14.6	Equipment requirements and periodic checks	42
14.7	Inspection procedure	42
15	Residual magnetism and demagnetization	42
15.1	General	42
15.2	Application	43
15.3	Services	43
16	Gamma-ray wall thickness inspection	44
16.1	General	44
16.2	Application	44
16.3	Equipment	44
16.4	Calibration and standardization	44
16.5	Inspection procedure	45
17	Electromagnetic grade comparison	45

17.1	General	45
17.2	Application	45
17.3	Equipment	45
17.4	Calibration and Standardization	45
17.5	Inspection procedure	46
18	Ultrasonic inspection	46
18.1	General	46
18.2	Application	47
18.3	General procedures for calibration, standardization, and inspection	47
18.4	Inspection for longitudinal, transverse, and oblique imperfections	48
18.5	Standardization	49
18.6	Procedure for the detection of longitudinal, transverse, and oblique imperfections	49
18.7	Inspection of the body wall for wall thinning	49
18.8	Ultrasonic inspection of longitudinal welds	50
18.9	Manual ultrasonic thickness gauging	52
18.10	Manual ultrasonic shear-wave inspection	54
19	Evaluation of imperfections and deviations	55
19.1	General	55
19.2	Application	55
19.3	Equipment	55
19.4	Calibration and standardization procedures	56
19.5	Procedure for evaluating outside-surface-breaking pipe body imperfections	56
19.6	Procedure for evaluating inside-surface-breaking pipe body imperfections	58
19.7	Procedure for evaluating welds	58
19.8	Procedure for evaluating grinds	59
19.9	Procedure for evaluating large-area wall reduction	59
19.10	Procedure for evaluating imperfections in upsets	60
19.11	Procedure for evaluation of outside surface imperfections on couplings	61
19.12	Procedure for evaluation of visually-located thread imperfections	61
19.13	Procedure for triangle location and coupling makeup position	64
19.14	Procedure for evaluating straightness	64
19.15	Procedure for evaluating pipe diameter	65
20	Hydrostatic pressure testing	65
20.1	General	65
20.2	Application	66
20.3	Equipment, safety, and general procedures	66
20.4	Equipment calibration	67
20.5	Operating procedure	67
21	Marking	68
21.1	General	68
21.2	Authority	69
21.3	Guidelines	69
21.4	Marking of prime OCTG	70
21.5	Marking of no-drift OCTG	70
21.6	Marking of conditioned OCTG	70
21.7	Marking of conditionable OCTG (still to be conditioned)	71
21.8	Marking of non-conditionable OCTG (rejects)	71
21.9	Marking of OCTG not meeting ISO/API standards for hardness	71
21.10	Marking of prime couplings and connectors	72
21.11	Marking of conditioned couplings and connectors	72
21.12	Marking of conditionable couplings and connectors (still to be conditioned)	72
21.13	Marking of non-conditionable couplings and connectors (rejects)	72
Annex A (normative) Tables in SI units		74
Annex B (normative) Figures		91
Annex C (normative) Tables in USC units		96
Bibliography		112