

ISO 2469:2007-06 (E)

Paper, board and pulps - Measurement of diffuse radiance factor

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	3
5 Apparatus	3
6 Photometric calibration of the instrument and its working standards	4
7 Sampling	5
8 Preparation of the test pieces	5
9 Procedure	5
10 Calculation and expression of results	6
11 Precision	6
12 Test report	6
Annex A (normative) Instruments for the measurement of radiance factor	8
Annex B (normative) Calibration service -- Photometric calibration	11
Annex C (normative) Calibration service -- UV-adjustment	13
Annex D (informative) Measurement uncertainty	15
Annex E (informative) Radiance and reflectance	18
Bibliography	19