

# ISO 5264-2:2011-02 (E)

## Pulps - Laboratory beating - Part 2: PFI mill method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Normative references</b> .....		1
3 <b>Principle</b> .....		1
4 <b>Apparatus and auxiliary materials</b> .....		1
5 <b>Sampling</b> .....		2
6 <b>Preparation of sample</b> .....		2
7 <b>Procedure</b> .....		2
8 <b>Test report</b> .....		4
<b>Annex A (normative) PFI mill</b> .....		5
<b>Annex B (normative) Control and maintenance of the PFI mill</b> .....		8
<b>Annex C (informative) Checking the stability of the PFI mill</b> .....		10
<b>Bibliography</b> .....		11