

ISO 7870-4:2011-07 (E)

Control charts - Part 4: Cumulative sum charts

| Contents | | Page |
|------------------------------|--|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions, abbreviated terms and symbols | 1 |
| 3.1 | Terms and definitions | 1 |
| 3.2 | Abbreviated terms | 2 |
| 3.3 | Symbols | 3 |
| 4 | Principal features of cumulative sum (cusum) charts | 4 |
| 5 | Basic steps in the construction of cusum charts -- Graphical representation | 5 |
| 6 | Example of a cusum plot -- Motor voltages | 5 |
| 6.1 | The process | 5 |
| 6.2 | Simple plot of results | 6 |
| 6.3 | Standard control chart for individual results | 7 |
| 6.4 | Cusum chart -- Overall perspective | 7 |
| 6.5 | Cusum chart construction | 8 |
| 6.6 | Cusum chart interpretation | 9 |
| 6.7 | Manhattan diagram | 12 |
| 7 | Fundamentals of making cusum-based decisions | 12 |
| 7.1 | The need for decision rules | 12 |
| 7.2 | The basis for making decisions | 13 |
| 7.3 | Measuring the effectiveness of a decision rule | 14 |
| 8 | Types of cusum decision schemes | 16 |
| 8.1 | V-mask types | 16 |
| 8.2 | Truncated V-mask | 16 |
| 8.3 | Alternative design approaches | 22 |
| 8.4 | Semi-parabolic V-mask | 23 |
| 8.5 | Snub-nosed V-mask | 24 |
| 8.6 | Full V-mask | 24 |
| 8.7 | Fast initial response (FIR) cusum | 25 |
| 8.8 | Tabular cusum | 25 |
| 9 | Cusum methods for process and quality control | 27 |
| 9.1 | The nature of the changes to be detected | 27 |
| 9.2 | Selecting target values | 28 |
| 9.3 | Cusum schemes for monitoring location | 29 |
| 9.4 | Cusum schemes for monitoring variation | 39 |
| 9.5 | Special situations | 47 |
| 9.6 | Cusum schemes for discrete data | 49 |
| Annex A (informative) | Von Neumann method | 56 |
| Annex B (informative) | Example of tabular cusum | 57 |

| | |
|---|-----------|
| Annex C (informative) Estimation of the change point when a step change occurs | 61 |
| Bibliography | 63 |