

ISO 3951-4:2011-08 (E)

Sampling procedures for inspection by variables - Part 4: Procedures for assessment of declared quality levels

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	2
3	Terms, definitions, symbols and abbreviations	2
4	Principles	3
5	Declared quality level (DQL)	4
6	Sampling plans	5
7	Operating a sampling plan	8
8	Further information	15
Annex A (informative) Method of matching variables plans to attributes plans		20
Annex B (informative) Examples of use of the procedures		21
Bibliography		25