

# ISO 28591:2017-10 (E)

## Sequential sampling plans for inspection by attributes

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	2
3	Terms and definitions .....	2
4	Symbols and abbreviated terms .....	6
5	Principles of sequential sampling plans for inspection by attributes .....	7
6	Selection of a sampling plan .....	7
6.1	Producer's risk point and consumer's risk point .....	7
6.2	Preferred values of QPR and QCR .....	8
6.3	Pre-operation preparations .....	8
6.3.1	Obtaining the parameters $h_A$ , $h_R$ and $g$ .....	8
6.3.2	Obtaining the curtailment values .....	8
7	Operation of a sequential sampling plan .....	8
7.1	Specification of the plan .....	8
7.2	Drawing a sample item .....	8
7.3	Count and cumulative count .....	8
7.3.1	Count .....	8
7.3.2	Cumulative count .....	8
7.4	Choice between numerical and graphical methods .....	8
7.5	Numerical method .....	9
7.5.1	Preparation of the acceptability table .....	9
7.5.2	Making decisions .....	9
7.6	Graphical method .....	10
7.6.1	Preparation of the acceptability chart .....	10
7.6.2	Making decisions .....	11
8	Numerical example .....	12
9	Tables .....	12
Annex A (informative)	Statistical properties of the sequential sampling plan for inspection by attributes .....	30
Bibliography .....		39