

# ISO 28591:2017-10 (E)

## Sequential sampling plans for inspection by attributes

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>2</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Symbols and abbreviated terms .....</b>	<b>6</b>
<b>5</b>	<b>Principles of sequential sampling plans for inspection by attributes .....</b>	<b>7</b>
<b>6</b>	<b>Selection of a sampling plan .....</b>	<b>7</b>
6.1	Producer's risk point and consumer's risk point .....	7
6.2	Preferred values of QPR and QCR .....	8
6.3	Pre-operation preparations .....	8
6.3.1	Obtaining the parameters $h_A$ , $h_R$ and $g$ .....	8
6.3.2	Obtaining the curtailment values .....	8
<b>7</b>	<b>Operation of a sequential sampling plan .....</b>	<b>8</b>
7.1	Specification of the plan .....	8
7.2	Drawing a sample item .....	8
7.3	Count and cumulative count .....	8
7.3.1	Count .....	8
7.3.2	Cumulative count .....	8
7.4	Choice between numerical and graphical methods .....	8
7.5	Numerical method .....	9
7.5.1	Preparation of the acceptability table .....	9
7.5.2	Making decisions .....	9
7.6	Graphical method .....	10
7.6.1	Preparation of the acceptability chart .....	10
7.6.2	Making decisions .....	11
<b>8</b>	<b>Numerical example .....</b>	<b>12</b>
<b>9</b>	<b>Tables .....</b>	<b>12</b>
<b>Annex A (informative)</b>	<b>Statistical properties of the sequential sampling plan for inspection by attributes .....</b>	<b>30</b>
<b>Bibliography .....</b>		<b>39</b>