

# ISO 7870-1:2019-11 (E)

## Control charts - Part 1: General guidelines

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Symbols and abbreviated terms .....</b>	<b>7</b>
4.1	Symbols .....	7
4.2	Abbreviated terms .....	8
<b>5</b>	<b>Concepts .....</b>	<b>8</b>
5.1	Control chart .....	8
5.2	Statistical control of a process .....	9
5.3	Acceptance of a process .....	9
5.4	Management of a process with a natural drift .....	9
5.5	Risks of decision errors .....	9
5.6	Design of data collection .....	10
5.6.1	General .....	10
5.6.2	Choice of characteristic .....	10
5.6.3	Measurement process evaluation .....	10
5.6.4	Subgroup selection .....	10
5.6.5	Subgroup size .....	11
5.6.6	Sampling frequency .....	11
5.7	Control charts for variables and attributes data .....	11
<b>6</b>	<b>Types of control charts .....</b>	<b>12</b>
<b>7</b>	<b>Charts for process stability .....</b>	<b>12</b>
7.1	General .....	12
7.2	Partial listing of Shewhart and related control charts .....	13
7.2.1	General .....	13
7.2.2	Charts using data from only one rational subgroup for each plotted value .....	13
7.2.3	Charts using data from more than one subgroup for each plotted value .....	14
7.2.4	Charts for non-independent (autocorrelated) observations .....	14
<b>8</b>	<b>Charts for process acceptance .....</b>	<b>15</b>
8.1	General .....	15
<b>9</b>	<b>Process adjustment .....</b>	<b>16</b>
Annex A (informative) Charting styles and colours for control charts .....		17
Bibliography .....		19