

ISO 7870-7:2020-02 (E)

Control charts - Part 7: Multivariate control charts

| Contents | | Page |
|------------------------------|---|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Abbreviated terms and symbols | 2 |
| 4.1 | Abbreviated terms | 2 |
| 4.2 | Symbols | 2 |
| 5 | Purpose and classification of multivariate control charts | 4 |
| 5.1 | Purpose and applying conditions for multivariate control charts | 4 |
| 5.2 | Classification of multivariate control charts | 5 |
| 6 | Multivariate control charts with unweighted averages for mean shift | 6 |
| 6.1 | General | 6 |
| 6.2 | Control charts for the process mean ($n > 1$) | 7 |
| 6.2.1 | χ^2 control chart when pre-specified parameter values are known | 7 |
| 6.2.2 | T^2 control chart when pre-specified parameter values are unknown | 8 |
| 6.3 | Control charts for the process mean ($n = 1$) | 8 |
| 6.3.1 | χ^2 control chart when pre-specified parameter values are known | 8 |
| 6.3.2 | T^2 control chart when pre-specified parameter values are unknown | 9 |
| 6.4 | Summary and selection of multivariate control charts with unweighted averages for mean shifts | 9 |
| 6.5 | Test for assignable causes | 10 |
| 7 | Multivariate control charts with weighted averages for mean shifts | 11 |
| 8 | Control charts for the process dispersion | 12 |
| 9 | Interpretation of an out-of-control signal | 13 |
| Annex A (informative) | Example of multivariate statistical process control | 14 |
| Annex B (informative) | Example of MEWMA control chart | 17 |
| Annex C (informative) | Estimation of μ and Σ | 23 |
| Bibliography | | 25 |