

ISO 18941:2017-07 (E)

Imaging materials - Colour reflection prints - Test method for ozone gas fading stability

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Requirements	3
5	Target selection	3
6	Measurements	4
6.1	Use of replicates and reference samples	4
6.2	Holding and measurement conditions	4
6.3	Measured attributes	5
6.3.1	Definition of density terms	5
6.3.2	Density attributes to be measured	5
6.3.3	Definitions of colorimetry terms	6
6.3.4	Colorimetry values to be measured	6
7	Calculations and computations	6
7.1	Computation of densitometric attributes	6
7.2	Density change in dmin patches	6
7.3	Percentage density change in primary colour patches	6
7.4	Percentage density change in secondary (mixed) colour patches	6
7.5	Percentage density change in composite neutral patch	6
7.6	Colour balance shift in composite neutral patch	7
7.7	Colour balance shift in secondary (mixed) colour patches	7
7.8	Colour balance in dmin patches by colorimetry	7
7.9	Effects of colorant fading and stain formation on colour photographs	7
8	Test methods -- Gas fading (ozone)	7
8.1	General	7
8.2	Apparatus	8
8.3	Test procedure	15
9	Test environment conditions	16
9.1	Humidity control calibration	16
9.2	Relative humidity	16
9.3	Temperature	16
9.4	Ozone concentration	16
10	Test report	17
10.1	General reporting requirements	17
10.2	Ozone test reporting	17
Annex A (informative)	Method for interpolation	19

Annex B (normative) Reciprocity considerations	20
Bibliography	22